



05 - STAGING  
INDEX OF DRAWINGS

DRAWING NUMBER	DRAWING TITLE	DRAWING NUMBER	DRAWING TITLE
GS-1A	STAGE PLAN 1A	GS-3H	STAGE PLAN 3H
GS-1B	STAGE PLAN 1B	GS-3I	STAGE PLAN 3I
GS-1C	STAGE PLAN 1C	ED-XXX	STAGING FOR STRUCTURE 371A
GS-1D	STAGE PLAN 1D	ED-XXX	STAGING FOR STRUCTURE 371A
GS-1E	STAGE PLAN 1E		
GS-2A	STAGE PLAN 2A		
GS-2B	STAGE PLAN 2B		
GS-2C	STAGE PLAN 2C		
GS-2D	STAGE PLAN 2D		
GS-2E	STAGE PLAN 2E		
GS-2F	STAGE PLAN 2F		
GS-2G	STAGE PLAN 2G		
GS-2H	STAGE PLAN 2H		
GS-3A	STAGE PLAN 3A		
GS-3B	STAGE PLAN 3B		
GS-3C	STAGE PLAN 3C		
GS-3D	STAGE PLAN 3D		
GS-3E	STAGE PLAN 3E		
GS-3F	STAGE PLAN 3F		
GS-3G	STAGE PLAN 3G		


## FINAL PLANS FOR REVIEW

-	-	-	-	THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK, SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE CONDITIONS OF ACTUAL QUANTITIES OF WORK WHICH WILL BE REQUIRED.	DESIGNER/DRAFTER: <b>R. KAYAN</b> CHECKED BY: <b>T. HOLLAND</b>	 <b>STATE OF CONNECTICUT</b> <b>DEPARTMENT OF TRANSPORTATION</b>	SIGNATURE/ BLOCK:	PROJECT TITLE:  <b>STAMFORD YARD CATENARY IMPROVEMENTS AND TRACK 7 EXTENSION</b>	TOWN:  <b>STAMFORD</b>	PROJECT NO.  <b>301-163</b>
-	-	-	-	Plotted Date: 3/26/2016					DRAWING TITLE:  <b>STAGING INDEX OF DRAWINGS</b>	DRAWING NO.  <b>IND-00</b> SHEET NO.  <b>02.05.000</b>
REV.	DATE	REVISION	DESCRIPTION	SHEET NO.	Plotted Date: 3/26/2016	Filename: ...\\MSH.0301.0163-TSH-V2-S05-1.dgn				

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.001

LEGEND:

TRACK IN SERVICE	
CONT. TRACK OUTAGE	
OFF-PEAK OUTAGE	



NOTE: STR. 384XA REQUIRED FOR NEW CARWASH CATENARY DEAD END.  
STR. 371, 372 AND 372B, DUE TO THE ADDITION OF TRACK 7.

STAGE	TASK	TRACK	TRACK OUTAGE
1	<p><u>OUTAGES FOR PREP WORK</u></p> <p>A) INSTALL NEW POLE &amp; STRUT (370X) B) INSTALL NEW SOUTH COLUMN (371) C) INSTALL NEW SOUTH COLUMN (372) D) INSTALL NEW SOUTH COLUMN (372B) E) INSTALL NEW FOUNDATION &amp; POLE (384XA) F) INSTALL NEW STEEL TRK 6, STR. 374 G) INSTALL CANTILEVER ASSEMBLIES 384A &amp; 384B H) INSTALL TRK 6 MESSENGER, STR. 370X TO 374</p>		OFF-PEAK NIGHTS

THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.



AECOM  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882



STATE OF CONNECTICUT  
DEPARTMENT OF TRANSPORTATION

STAMFORD YARD  
CATENARY IMPROVEMENTS  
AND TRACK 7 EXTENSION

STAGE PLAN 1A

ENGINEER: AECOM

DESIGNER: RW

DRAFTER: AMK

CHECKER: RK/MR

APPROVED: T. HOLLAND

DATE: 03/30/16

STRUCTURE NO.

BRIDGE LOG NO.

STRUCTURE SHEET NO.


GS-1A

PROJECT CONTROL DATE: 03/30/2016      DISK FILENAME: GS-SHEET\_1 (1B).DWG      100% DESIGN

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.002

LEGEND:

TRACK IN SERVICE	
CONT. TRACK OUTAGE	
OFF-PEAK OUTAGE	



COORDINATE WITH WEEKEND ATLANTIC STREET WORK

NOTE: AFTER THIS PHASE OF CONSTRUCTION, ALL YARD TRACK ARE BACK IN SERVICES.

STAGE	TASK	TRACK	TRACK OUTAGE
2	A) INSTALL TEMP. DEAD END STEEL AT STR. 379. ON TRK 8, TERMINATE EXIST TRK 8 CATENARY ON EAST SIDE. B) REMOVE EXISTING TRK 8 CATENARY, BETWEEN 374 TO TEMP. STEEL AT 379. C) INSTALL DROP TUBE SUPPORT STEEL & D.T.'S AT 375. D) INSTALL CANTILEVER ASSEMBLY AT 374C. E) LOWER TRK 10 AND 12 TO DESIGN HEIGHT BETWEEN STR. 374 - 377. F) ADJUST ALL DROP TUBE HEIGHTS TRK 8, 374A TO 378. G) INSTALL NEW TRK 8 CATENARY 374A TO 379. H) SPLICE NEW CONTACT WIRE TO EXISTING AT STR. 379. I) INSTALL SECTION INSULATORS AT STR. 375 AND 379 AND INSTALL SWITCH TAPS.	6,8,10,12	CONTINUOUS WEEKEND OUTAGE, SATURDAY 1 AM TO SUNDAY 5 PM

THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

AECOM

500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		

STATE OF CONNECTICUT  
DEPARTMENT OF TRANSPORTATION

STAMFORD YARD  
CATENARY IMPROVEMENTS  
AND TRACK 7 EXTENSION


STAGE PLAN 1B

ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO. STRUCTURE SHEET NO. GS-1B

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.003

LEGEND:

TRACK IN SERVICE	
CONT. TRACK OUTAGE	
OFF-PEAK OUTAGE	



COORDINATE WITH WEEKEND ATLANTIC STREET WORK

STAGE	TASK	TRACK	TRACK OUTAGE
3	A) INSTALL NEW SWITCH, SUPPORTING STEEL AND LINKAGE FOR TRACK 6.		OFF PEAK DAY OUTAGE
	B) INSTALL NEW SWITCH, SUPPORTING STEEL AND LINKAGE FOR TRACK 8.		OFF PEAK DAY OUTAGE
	C) INSTALL NEW SWITCH, SUPPORTING STEEL AND LINKAGE FOR TRACK 10.		OFF PEAK DAY OUTAGE


- NOTE: 1) CARWASH OUT OF SERVICE AFTER THIS PHASE.  
2) 68 AND 86 CROSSOVERS OUT OF SERVICE AFTER THIS PHASE.  
3) TRACK 8 EAST OF STR. 384 IS OUT OF SERVICE AFTER THIS PHASE.

THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM**

**AECOM**  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		



STATE OF CONNECTICUT  
DEPARTMENT OF TRANSPORTATION

STAMFORD YARD  
CATENARY IMPROVEMENTS  
AND TRACK 7 EXTENSION


STAGE PLAN 1C

ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO. STRUCTURE SHEET NO. GS-1C

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.004

LEGEND:

TRACK IN SERVICE	
CONT. TRACK OUTAGE	
OFF-PEAK OUTAGE	



COORDINATE WITH WEEKEND ATLANTIC STREET WORK

STAGE	TASK	TRACK	TRACK OUTAGE
3A	<p>A) REMOVE 68 AND 86 CROSSOVER CATENARY BETWEEN STR. 379 TO STR. 382.</p> <p>B) REMOVE TRK 6 EXISTING CATENARY BETWEEN STR. 374 TO 387.</p> <p>C) INSTALL DROP TUBE SUPPORT STEEL &amp; D.T. AT STR. 375.</p> <p>D) ADJUST ALL DROP TUBE HEIGHTS TRK 6 374 - 384.</p> <p>E) INSTALL CANTILEVER ASSEMBLIES 374A &amp; 384A.</p> <p>F) LIMITS INSTALL NEW TRACK 6 CATENARY. MESSENGER FROM 374 TO 387.</p> <p>G) INSTALL SECTION INSULATORS AT STR. 373, 375, 381 &amp; 384.</p> <p>H) INSTALL SWITCH TAPS AND JUMPERS.</p>	6,8,10,12 L1 & CAR WASH	CONTINUOUS WEEKEND OUTAGE, SATURDAY 1 AM TO SUNDAY 5 PM

NOTE: 1) CARWASH OUT OF SERVICE AFTER THIS PHASE.  
2) 68 AND 86 CROSSOVERS OUT OF SERVICE AFTER THIS PHASE.  
3) TRACK 8 EAST OF STR. 384 IS OUT OF SERVICE AFTER THIS PHASE.

THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.




			STAGE PLAN 1D		
			ENGINEER: AECOM		
			DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
NO.	DATE	DESCRIPTION	APPROVED: T. HOLLAND		
			DATE: 03/30/16		
REVISIONS			STRUCTURE NO.		BRIDGE LOG NO.
					STRUCTURE SHEET NO. GS-1D

PROJECT CONTROL DATE: 03/30/2016  
DISK FILENAME: GS-SHEET\_1 (1E).DWG  
100% DESIGN

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.005

LEGEND:

TRACK IN SERVICE	
CONT. TRACK OUTAGE	
OFF-PEAK OUTAGE	



COORDINATE WITH WEEKEND ATLANTIC STREET WORK

NOTE: 1) CARWASH AND 68 CROSSOVER OUT OF SERVICE AFTER THIS PHASE.

STAGE	TASK	TRACK	TRACK OUTAGE
4	A) REMOVE TRK 8 CATENARY FROM STR. 379 TO 385.  B) REMOVE L1 CATENARY FROM STR. SY16 TO 381. C) REMOVE CARWASH CATENARY STR. 380 TO 383. D) INSTALL NEW L1 / 86 CROSSOVER CATENARY FROM STR. SY16 TO 382. E) LOWER TRACK 10 & 12 CATENARY STR. 378 - 380. F) INSTALL NEW TRK 8 CATENARY STR. 379 TO 387X. G) INSTALL SECTION INSULATION AT STR. 381, 384 AND CROSSOVER 86. H) INSTALL SWITCH TAPS AND JUMPERS. I) COMPLETE DISC. SWITCH AT STR. 375.	6,8,10,12 L1 & CAR WASH	CONTINUOUS WEEKEND OUTAGE, SATURDAY 1 AM TO SUNDAY 5 PM

THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.



AECOM  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		


STAMFORD YARD CATENARY IMPROVEMENTS AND TRACK 7 EXTENSION		
STAGE PLAN 1E		
ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO. STRUCTURE SHEET NO. GS-1E

PROJECT CONTROL DATE: 03/30/2016      DISK FILENAME: GS-SHEET\_1 (1F).DWG      100% DESIGN

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.006

LEGEND:

TRACK IN SERVICE	
CONT. TRACK OUTAGE	
OFF-PEAK OUTAGE	



COORDINATE WITH WEEKEND ATLANTIC STREET WORK


STAGE	TASK	TRACK	TRACK OUTAGE
5	A) INSTALL 68 CROSSOVER CATENARY STR. 379 TO 380X.  B) INSTALL NEW CARWASH CATENARY 380 TO 384XA. C) RE-INSTALL SWITCHING ARRANGEMENT AT 381E.	6,8,10,12 L1 & CAR WASH	CONTINUOUS WEEKEND OUTAGE, SATURDAY 1 AM TO SUNDAY 5 PM

THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM**

**AECOM**  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		




STATE OF CONNECTICUT  
DEPARTMENT OF TRANSPORTATION

STAMFORD YARD  
CATENARY IMPROVEMENTS  
AND TRACK 7 EXTENSION

STAGE PLAN 1F

ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO. STRUCTURE SHEET NO. GS-1F

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.007



LEGEND:

TRACK IN SERVICE	—————	BRIDGE CONSTRUCTION	
CONT. TRACK OUTAGE	—————		
OFF-PEAK OUTAGE	- - - - -		
BRIDGE PLATES		TEMPORARY PLATFORM	

COORDINATE WITH ATLANTIC STREET NORTH SIDE RETAINING WALL WORK.

STAGE	* TASK	TRACK	TRACK OUTAGE
1	1) INSTALL NORTH FOUNDATION AND COLUMNS FOR STR. 370A, 370B, 371, 371A, 372, 372A, 372B AND D.E. POLE (TBD).  2) THREE GUY ANCHORS: (1) EAST OF NEW 372 (1) WEST OF NEW 371 (1) WEST OF D.E. POLE	5, 7  5, 7	OFF PEAK NIGHTS  OFF PEAK NIGHTS


THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM**  
AECOM  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		

<b>STATE OF CONNECTICUT</b> DEPARTMENT OF TRANSPORTATION		
STAMFORD YARD CATENARY IMPROVEMENTS AND TRACK 7 EXTENSION		
STAGE PLAN 2A		
ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO. STRUCTURE SHEET NO. CS-2A

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.008



LEGEND:

TRACK IN SERVICE	—	BRIDGE CONSTRUCTION	
CONT. TRACK OUTAGE	—	TEMPORARY PLATFORM	
OFF-PEAK OUTAGE	- - -		
BRIDGE PLATES			

STAGE	* TASK	TRACK	TRACK OUTAGE
2	1) INSTALL TRUSS FOR STRUCTURES 371, 372 AND 372B.  2) INSTALL POLE EXTENSION ON TRUSS AND TRANSFER FEEDERS.		4 TRACK WEEKEND NIGHT OUTAGE (3 NIGHTS REQUIRED)


THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM**  
AECOM  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		

 STATE OF CONNECTICUT DEPARTMENT OF TRANSPORTATION		
STAMFORD YARD CATENARY IMPROVEMENTS AND TRACK 7 EXTENSION		
STAGE PLAN 2B		
ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO. STRUCTURE SHEET NO. GS-2B

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.009




STAGE	* TASK	TRACK	TRACK OUTAGE
3	1) INSTALL NEW OCS SUPPORT STEEL ON 371, 372 AND 372B.	6	OFF PEAK DAY OUTAGE


THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.



NO.	DATE	DESCRIPTION
REVISIONS		

	STATE OF CONNECTICUT DEPARTMENT OF TRANSPORTATION		
	STAMFORD YARD CATENARY IMPROVEMENTS AND TRACK 7 EXTENSION		
	STAGE PLAN 2C		
	ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR	
APPROVED: T. HOLLAND		DATE: 03/30/16	
STRUCTURE NO.	BRIDGE LOG NO.	STRUCTURE SHEET NO. GS-2C	

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.010



LEGEND:

TRACK IN SERVICE		BRIDGE CONSTRUCTION	
CONT. TRACK OUTAGE		TEMPORARY PLATFORM	
OFF-PEAK OUTAGE			
BRIDGE PLATES			

STAGE	* TASK	TRACK	TRACK OUTAGE
4	1) INSTALL NEW OCS SUPPORT STEEL ON 371, 372 AND 372B.	4,2	OFF PEAK NIGHT OUTAGE


THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM**  
AECOM  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		

 STATE OF CONNECTICUT DEPARTMENT OF TRANSPORTATION		
STAMFORD YARD CATENARY IMPROVEMENTS AND TRACK 7 EXTENSION		
STAGE PLAN 2D		
ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO. STRUCTURE SHEET NO. GS-2D

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.011



LEGEND:

TRACK IN SERVICE		BRIDGE CONSTRUCTION	
CONT. TRACK OUTAGE		TEMPORARY PLATFORM	
OFF-PEAK OUTAGE			
BRIDGE PLATES			

STAGE	* TASK	TRACK	TRACK OUTAGE
5	1) INSTALL NEW OCS SUPPORT STEEL ON 371, 372 AND 372B.	1,3	OFF PEAK NIGHT OUTAGE


THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM**  
AECOM  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		

<b>STATE OF CONNECTICUT</b> DEPARTMENT OF TRANSPORTATION		
STAMFORD YARD CATENARY IMPROVEMENTS AND TRACK 7 EXTENSION		
STAGE PLAN 2E		
ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO. STRUCTURE SHEET NO. GS-2E

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.012



LEGEND:

TRACK IN SERVICE	—————	BRIDGE CONSTRUCTION	
CONT. TRACK OUTAGE	—————		
OFF-PEAK OUTAGE	- - - - -		
BRIDGE PLATES		TEMPORARY PLATFORM	

STAGE	* TASK	TRACK	TRACK OUTAGE
6	1) INSTALL NEW OCS SUPPORT STEEL ON 371, 372 AND 372B.	5,7	OFF PEAK NIGHT OUTAGE

THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.


**AECOM**  
AECOM  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		

 STATE OF CONNECTICUT DEPARTMENT OF TRANSPORTATION		
STAMFORD YARD CATENARY IMPROVEMENTS AND TRACK 7 EXTENSION		
STAGE PLAN 2F		
ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO. STRUCTURE SHEET NO. GS-2F

PROJECT CONTROL DATE: 03/30/2016      DISK FILENAME: ATLANTIC Constr Stg\_2(20).DWG00% DESIGN

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.013



LEGEND:

TRACK IN SERVICE	—————	BRIDGE CONSTRUCTION	
CONT. TRACK OUTAGE	—————		
OFF-PEAK OUTAGE	- - - - -		
BRIDGE PLATES		TEMPORARY PLATFORM	

STAGE	* TASK	TRACK	TRACK OUTAGE
7	1) TRANSFER CATENARY FIXED ANCHOR FOR WR 11 FROM NORTH COLUMN OF 371A TO NORTH COLUMN OF NEW 372.	5	OFF PEAK NIGHT OUTAGE
	2) TRANSFER CATENARY FIXED ANCHOR FOR WR 17 FROM NORTH COLUMN OF 370A TO NEW D.E. POLE.	5	OFF PEAK NIGHT OUTAGE
	3) TRANSFER CATENARY FIXED ANCHOR FOR WR 18 FROM NORTH COLUMN OF 371A TO NORTH COLUMN OF NEW 371.	5,7	OFF PEAK NIGHT OUTAGE


THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM**  
AECOM  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		

STATE OF CONNECTICUT DEPARTMENT OF TRANSPORTATION		
STAMFORD YARD CATENARY IMPROVEMENTS AND TRACK 7 EXTENSION		
STAGE PLAN 2G		
ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO.      STRUCTURE SHEET NO. GS-2G

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.014



LEGEND:

TRACK IN SERVICE	—	BRIDGE CONSTRUCTION	
CONT. TRACK OUTAGE	—		
OFF-PEAK OUTAGE	- - -		
BRIDGE PLATES		TEMPORARY PLATFORM	

STAGE	* TASK	TRACK	TRACK OUTAGE
8	INSTALL TRUSS EXTENSION FOR STR. 370A, 370B, 371A AND 372A.	5,3,1, 2,4	ONE WEEKEND NIGHT OUTAGE PER STRUCTURE (SEE STAGE _____ FOR DETAILS.)

THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM**  
AECOM  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882


NO.	DATE	DESCRIPTION
REVISIONS		

 STATE OF CONNECTICUT DEPARTMENT OF TRANSPORTATION		
STAMFORD YARD CATENARY IMPROVEMENTS AND TRACK 7 EXTENSION		
STAGE PLAN 2H		
ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO. STRUCTURE SHEET NO. GS-2H

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.015

LEGEND:

TRACK IN SERVICE		BRIDGE CONSTRUCTION	
CONT. TRACK OUTAGE			
OFF-PEAK OUTAGE			
BRIDGE PLATES		TEMPORARY PLATFORM	



STAGE	TASK	TRACK	TRACK OUTAGE
1	1) LOWER TRACK 1 BETWEEN STR. 371A TO STR. 372B BY LOWERING DROP TUBE ASSEMBLIES BY 1'-3" TO 1'-6" AT STR. 372 AND STR. 372A.  2) ADJUST 31 CROSSOVER AND LEVEL SECTION INSULATOR.  3) ADJUST 12 CROSSOVER AND LEVEL SECTION INSULATOR.	1	OFF PEAK NIGHT OUTAGE (1 AM - 4:30 AM)

NOTE:  
LADDER CROSSOVERS MUST BE BACK IN SERVICE AT END OF EACH WORK SHIFT.

THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM**

**AECOM**  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		

**STATE OF CONNECTICUT**  
DEPARTMENT OF TRANSPORTATION

STAMFORD YARD  
CATENARY IMPROVEMENTS  
AND TRACK 7 EXTENSION


STAGE PLAN 3A

ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO.
		STRUCTURE SHEET NO. CS-3A

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.016

LEGEND:

TRACK IN SERVICE		BRIDGE CONSTRUCTION	
CONT. TRACK OUTAGE		TEMPORARY PLATFORM	
OFF-PEAK OUTAGE			
BRIDGE PLATES			



NOTE:  
LADDER CROSSOVERS MUST BE BACK IN SERVICE AT END OF EACH WORK SHIFT.

STAGE	TASK	TRACK	TRACK OUTAGE
2	1) LOWER TRACK 2 BETWEEN STR. 372A TO STR. 373 BY LOWERING DROP TUBE ASSEMBLIES ON STR. 372B BY 1'-0" ±.  2) ADJUST 12 CROSSOVER AND LEVEL SECTION INSULATOR.  3) ADJUST 24 CROSSOVER AND LEVEL SECTION INSULATOR.  4) STR. 372XA ADJUST SBA ASSEMBLIES AS REQUIRED.	2	OFF PEAK NIGHT OUTAGE (1 AM - 4:30 AM)

THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM**

**AECOM**  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		


**STATE OF CONNECTICUT**  
DEPARTMENT OF TRANSPORTATION

STAMFORD YARD  
CATENARY IMPROVEMENTS  
AND TRACK 7 EXTENSION


STAGE PLAN 3B

ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO.
		STRUCTURE SHEET NO. GS-3B

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.017

LEGEND:

TRACK IN SERVICE		BRIDGE CONSTRUCTION	
CONT. TRACK OUTAGE		TEMPORARY PLATFORM	
OFF-PEAK OUTAGE			
BRIDGE PLATES			



STAGE	TASK	TRACK	TRACK OUTAGE
3	1) LOWER TRACK 2 BETWEEN STR. 371 AND STR. 372B BY LOWERING DROP TUBE ASSEMBLIES AT STR. 371A BY 11"± AND AT STR. 372A BY 1'-0" TO 1'-3".  2) LOWER TRACK 4 BETWEEN STR. 371 AND 372B BY LOWERING DROP TUBE ASSEMBLIES AT STR. 371 BY 9"± AND AT STR. 371A BY 1'-0"±.  3) CHECK AND ADJUST MAINLINE OVERLAP ON TRACK 4.  4) ADJUST 42 CROSSOVER AND LEVEL SECTION INSULATOR.	2 & 4	OFF PEAK NIGHT OUTAGE (1 AM - 4:30 AM)

NOTE:  
LADDER CROSSOVERS MUST BE BACK IN SERVICE AT END OF EACH WORK SHIFT.

THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM**  
AECOM  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		


STATE OF CONNECTICUT DEPARTMENT OF TRANSPORTATION		
STAMFORD YARD CATENARY IMPROVEMENTS AND TRACK 7 EXTENSION		
STAGE PLAN 3C		
ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO. STRUCTURE SHEET NO. GS-3C



F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.019

LEGEND:

TRACK IN SERVICE		BRIDGE CONSTRUCTION	
CONT. TRACK OUTAGE		TEMPORARY PLATFORM	
OFF-PEAK OUTAGE			
BRIDGE PLATES			



STAGE	TASK	TRACK	TRACK OUTAGE
5	1) LOWER TRACK 1 BETWEEN STR. 370B AND STR. 373A BY LOWERING DROP TUBE ASSEMBLIES TO OBTAIN APPROX. 18'-0" CONTACT WIRE HEIGHT AT STR. 371 TO STR. 373A.  2) ADJUST 31 CROSSOVER AND LEVEL SECTION INSULATOR.  3) ADJUST 12 CROSSOVER AND LEVEL SECTION INSULATOR.	1	OFF PEAK NIGHT OUTAGE (1 AM - 4:30 AM)

NOTE:  
LADDER CROSSOVERS MUST BE BACK IN SERVICE AT END OF EACH WORK SHIFT.

THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM**

**AECOM**  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		

**STATE OF CONNECTICUT**  
DEPARTMENT OF TRANSPORTATION

STAMFORD YARD  
CATENARY IMPROVEMENTS  
AND TRACK 7 EXTENSION


STAGE PLAN 3E

ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO.
		STRUCTURE SHEET NO. GS-3E

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.020

LEGEND:

TRACK IN SERVICE		BRIDGE CONSTRUCTION	
CONT. TRACK OUTAGE			
OFF-PEAK OUTAGE			
BRIDGE PLATES		TEMPORARY PLATFORM	



NOTE:  
LADDER CROSSOVERS MUST BE BACK IN SERVICE AT END OF EACH WORK SHIFT.

STAGE	TASK	TRACK	TRACK OUTAGE
6	1) LOWER TRACK 3 BETWEEN STR. 369B TO STR. 372B BY LOWERING DROP TUBE ASSEMBLIES TO OBTAIN APPROX. 18'-0" CONTACT WIRE HEIGHT AT STR. 369B TO STR. 372A.  2) ADJUST 53 CROSSOVER AND LEVEL SECTION INSULATOR.  3) ADJUST 31 CROSSOVER AND LEVEL SECTION INSULATOR.  4) ADJUST 35 CROSSOVER AND LEVEL SECTION INSULATOR.	3	OFF PEAK NIGHT OUTAGE (1 AM - 4:30 AM)

THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM**

AECOM

500 ENTERPRISE DRIVE

ROCKY HILL, CT 06067

1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		

STATE OF CONNECTICUT

DEPARTMENT OF TRANSPORTATION

STAMFORD YARD  
CATENARY IMPROVEMENTS  
AND TRACK 7 EXTENSION


STAGE PLAN 3F

ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO. STRUCTURE SHEET NO. GS-3F

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.021

LEGEND:

TRACK IN SERVICE		BRIDGE CONSTRUCTION	
CONT. TRACK OUTAGE		TEMPORARY PLATFORM	
OFF-PEAK OUTAGE			
BRIDGE PLATES			



NOTE:  
LADDER CROSSOVERS MUST BE BACK IN SERVICE AT END OF EACH WORK SHIFT.


STAGE	TASK	TRACK	TRACK OUTAGE
7	1) LOWER TRACK 4 BETWEEN STR. 371B TO STR. 374 BY LOWERING DROP TUBE ASSEMBLIES TO OBTAIN APPROX. 18'-0" CONTACT WIRE HEIGHT AT STR. 372A TO STR. 373A.  2) CHECK AND ADJUST MAINLINE OVERLAP AS REQUIRED.  3) ADJUST 24 CROSSOVER AND LEVEL SECTION INSULATOR.  4) ADJUST 46 CROSSOVER AND LEVEL SECTION INSULATOR.	4	OFF PEAK NIGHT OUTAGE (1 AM - 4:30 AM)

THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM**

**AECOM**  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		



STATE OF CONNECTICUT  
DEPARTMENT OF TRANSPORTATION

STAMFORD YARD  
CATENARY IMPROVEMENTS  
AND TRACK 7 EXTENSION


STAGE PLAN 3G

ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO. STRUCTURE SHEET NO. GS-3G

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.022

LEGEND:

TRACK IN SERVICE		BRIDGE CONSTRUCTION	
CONT. TRACK OUTAGE		TEMPORARY PLATFORM	
OFF-PEAK OUTAGE			
BRIDGE PLATES			



NOTE:  
LADDER CROSSOVERS MUST BE BACK IN SERVICE AT END OF EACH WORK SHIFT.

STAGE	TASK	TRACK	TRACK OUTAGE
8	1) LOWER TRACK 2 BETWEEN STR. 371B TO STR. 374 BY LOWERING DROP TUBE ASSEMBLIES TO OBTAIN APPROX. 18'-0" CONTACT WIRE HEIGHT AT STR. 372A TO STR. 373A.  2) ADJUST 42 CROSSOVER AND LEVEL SECTION INSULATOR.  3) ADJUST 12 CROSSOVER AND LEVEL SECTION INSULATOR.  4) ADJUST 24 CROSSOVER AND LEVEL SECTION INSULATOR.  5) ADJUST 21 CROSSOVER AND LEVEL SECTION INSULATOR.	2	OFF PEAK NIGHT OUTAGE (1 AM - 4:30 AM)

THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM**

AECOM

500 ENTERPRISE DRIVE

ROCKY HILL, CT 06067

1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		

STATE OF CONNECTICUT

DEPARTMENT OF TRANSPORTATION

STAMFORD YARD  
CATENARY IMPROVEMENTS  
AND TRACK 7 EXTENSION

STAGE PLAN 3H

ENGINEER: AECOM

DESIGNER: RW

DRAFTER: AMK

CHECKER: RK/MR

APPROVED: T. HOLLAND

DATE: 03/30/16

STRUCTURE NO.


BRIDGE LOG NO.

STRUCTURE SHEET NO.  
GS-3H

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.023

LEGEND:

TRACK IN SERVICE		BRIDGE CONSTRUCTION	
CONT. TRACK OUTAGE			
OFF-PEAK OUTAGE			
BRIDGE PLATES		TEMPORARY PLATFORM	



STAGE	TASK	TRACK	TRACK OUTAGE
9	1) LOWER TRACK 1 BETWEEN STR. 372A TO STR. 375 BY LOWERING DROP TUBE ASSEMBLIES TO OBTAIN APPROX. 18'-0" CONTACT WIRE HEIGHT AT STR. 372B AND STR. 373A.  2) ADJUST 21 CROSSOVER AND LEVEL SECTION INSULATOR.	1	OFF PEAK NIGHT OUTAGE (1 AM - 4:30 AM)

NOTE:  
LADDER CROSSOVERS MUST BE BACK IN SERVICE AT END OF EACH WORK SHIFT.

THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM**

**AECOM**  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		




**STATE OF CONNECTICUT**  
DEPARTMENT OF TRANSPORTATION

STAMFORD YARD  
CATENARY IMPROVEMENTS  
AND TRACK 7 EXTENSION

STAGE PLAN 3I

ENGINEER: AECOM		
DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
APPROVED: T. HOLLAND		DATE: 03/30/16
STRUCTURE NO.		BRIDGE LOG NO. STRUCTURE SHEET NO. GS-3I

F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.024



NOTES FOR EXISTING CONDITIONS:

- PREP WORK: MEASURE AND NOTE CATENARY (DROP TUBE) SUPPORT STEEL LOCATION AND TRANSFER MEASUREMENT TO NEW TRUSS SECTION.

NOTES FOR STEP 1:

- COORDINATE WITH ATLANTIC STREET SITE WORK FOR FOUNDATION WORK.
- NORTH SIDE COLUMN INSTALLATION.
- TRUSS REINFORCEMENT (SEE STAGE \_\_\_\_\_).
- TRANSFER CATENARY TERMINATION AS REQUIRED (SEE STAGE \_\_\_\_\_).
- TRANSFER C&S CABLES TO NEW NORTH COLUMN.
- DROP TUBE SUPPORT STEEL INSTALLED IN PROPER LOCATION ON NEW TRUSS SECTION (DROP TUBES MARKED BUT NOT INSTALLED).

NOTES FOR STEP 2:

- REMOVE EXISTING DOWN GUYS.
- INSTALL WOOD POLE WITH CROSSARMS TO TEMPORARY SUPPORT RAILROAD FEEDERS AND SIGNALS WIRES.
- TRANSFER FEEDERS AND SIGNAL WIRES TO WOOD POLE.
- REMOVE POLE TOP EXTENSION (TO BE REMOUNTED ON NEW TRUSS EXTENSION).



STATE OF CONNECTICUT  
DEPARTMENT OF TRANSPORTATION

STAMFORD YARD  
CATENARY IMPROVEMENTS  
AND TRACK 7 EXTENSION

STAGING FOR STRUCTURE 371A  
(370A, 370B AND 372A SIMILAR)

ENGINEER: AECOM
-----------------

DESIGNER: RW

DRAFTER: AMK

CHECKER: RK/MR

APPROVED: T. HOLLAND

DATE: 03/30/16

STRUCTURE NO.	
---------------	--

BRIDGE LOG NO.	STRUCTURE SHEET 1
	FD-300

STRUCTURE NO.: \_\_\_\_\_

	ED-XXX
--	--------

DISK FILENAME: ED-371A\_(EXIST.-STEP 2).dwg100% DESIGN



PROJECT CONTROL DATE: 03/30/2016

THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM** *AECOM*  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

NO.	DATE	DESCRIPTION
REVISIONS		


F H W A REGION	STATE	TOWN	FED. AID PROJ. NO.	PROJ. NO.	YEAR	SHEET NUMBER
1	CONN.	STAMFORD		135-163	2016	02.05.025



- NOTES FOR STEP 3:
- POSITION CRANE 1 ON TRACK 1, EAST OF STRUCTURE TO PICK AND HOLD EXISTING TRUSS SOUTH OF SPLICE LOCATION.
  - POSITION CATENARY SUPPORT POLES ON TRACK 3 AND 5, WEST OF STRUCTURE TO HOLD TRACK 3 AND 5 CATENARY.
  - POSITION CRANE 2 ON TRACK 5, EAST OF STRUCTURE, TO PICK AND REMOVE TRUSS SECTION AND OLD NORTH COLUMN.
  - BUCKET TRUCKS ON TRACKS 3 AND 5, TO ASSIST WITH RELEASING, CATENARY AND WORKING SPLICE AND COLUMN CONNECTIONS.
  - CRANE 2 PICKS AND SETS NEW TRUSS SECTION.

- NOTES FOR STEP 4:
- INSTALL CATENARY DROP TUBES AND SUPPORT AND REGISTER CATENARY TRACKS 3 AND 5
  - INSPECT CATENARY ON TRACKS 3 AND 5.

- NOTES FOR FINAL CONDITION:
- INSTALL POLE TOP EXTENSION ON TRUSS.
  - TRANSFER FEEDERS AND SIGNALS WIRES TO TRUSS.
  - REMOVE WOOD POLES.



THE INFORMATION, INCLUDING ESTIMATED QUANTITIES OF WORK SHOWN ON THESE SHEETS IS BASED ON LIMITED INVESTIGATIONS BY THE STATE AND IS IN NO WAY WARRANTED TO INDICATE THE TRUE CONDITIONS OR ACTUAL QUANTITIES OR DISTRIBUTION OF QUANTITIES OF WORK WHICH WILL BE REQUIRED.

**AECOM** *AECOM*  
500 ENTERPRISE DRIVE  
ROCKY HILL, CT 06067  
1-(860)-529-8882

			DRAWING FOR STRUCTURE 371A (370A, 370B AND 372A SIMILAR)		
			ENGINEER: AECOM		
			DESIGNER: RW	DRAFTER: AMK	CHECKER: RK/MR
NO.	DATE	DESCRIPTION	APPROVED: T. HOLLAND		DATE: 03/30/16
REVISIONS			STRUCTURE NO.		BRIDGE LOG NO. STRUCTURE SHEET NO. ED-XXX

DISK FILENAME: ED-371A\_(STAGE 3-NEW).dwg 100% DESIGN

PROJECT CONTROL DATE: 03/30/2016